



Railroad Commission of Texas
Oil and Gas Division
Field Operations

Inspection Report
 Field Initiated Inspection
 Inspection ID 61294

Operator	FAIRWAY RESOURCES OPERATING, LLC (259788)	Drilling Permit	_____
Lease/Facility	COOK, J. T. "A" [09-095018]	Pit Permit	_____
Field	PERRIN, SW (CONGL 4850) [70655500]	UIC Number	_____
County	PALO PINTO		
Complainant	_____		
GPS Coordinates	Geodetic Datum: WGS 84, 32.0007 N, -98.1521 W		

Statewide Rules Inspected

Lease Level Inspection

SWR Rule	Compliance	Compliance Description
SWR 2(a), Access to Property	Compliant	
SWR 3(1), Entrance Sign	Compliant	
SWR 3(3), Battery Sign; Commingling Permit	Compliant	
SWR 8(d)(1), Unpermitted Disposal of Oil and Gas Wastes	Compliant	
SWR 8(d)(2), Unpermitted Use of Pit	N/A	
SWR 21(j), Dike or Fire Wall Requirements	Compliant	
SWR 22(b), Bird Protection	N/A	
SWR 32(h), Permit Required for Flaring	N/A	
SWR 36(c)(5)(B), Storage Tank Warning Sign	N/A	
SWR 91(d)(1), Remediation of Soil	N/A	

Well Level Inspection

2

API 36332462

SWR Rule	Compliance	Compliance Description
SWR 3(2), Well Sign	Compliant	
SWR 8(d)(1), Unpermitted Disposal of Oil and Gas Wastes	Compliant	
SWR 8(d)(2), Unpermitted Use of Pit	N/A	
SWR 8(d)(4)(H)(i), Pit Backfill Requirements	N/A	
SWR 9(1), Permit Required for Disposal Well	N/A	
SWR 13(a)(6)(A), Surface Control of Well	Compliant	
SWR 14(b)(2), Inactive Unplugged Well	Non-compliant	WELL NOT ACTIVE. NOT CONNECTED TO FLOW LINES.
SWR 17(a), Bradenhead Requirements	Compliant	SURFACE - 0 PSI. VALVES OPEN UPON ARRIVAL.
SWR 46(a), Permit Required for Injection Well	N/A	
SWR 73(i), Producing, Injecting, Disposing Under Severance	N/A	
SWR 91(d)(1), Remediation of Soil	N/A	

Comments

FENCE HAS BEEN CONSTRUCTED AROUND WELL.

Inspector Information and Certification

I certify that the data included in this inspection is true and complete.

Inspector: SHANNA SMITH

Date: 01/25/2016

Start:

End:

Mileage

109983

109989

Time

11:30

12:00

Lunch

0 (Min)

Office Review

Reviewed By Gene Ortiz (258)

Reviewed Date

01/26/2016

FAIRWAY RESOURCES OPERATING
COOK, J.T. "A"
WELL #2 (095018)
PALO PINTO COUNTY



PHOTO #5992 – VIEW OF SIGN AT WELL #2.



PHOTO #5993 – VIEW OF BRADENHEAD GAUGE.